

# Tech Help

**Applications:** All 2001 and newer Volvo 60, 70, and 80 Series

**GSP Part Numbers:** NCV73500, NCV73503, NCV73504, NCV73511,  
NCV73512, NCV73514, NCV73515, NCV73518,  
NCV73519, NCV73522, NCV73523, NCV73528,  
NCV73530, NCV73531, NCV73532, NCV73533,  
NCV73541, NCV73542, NCV73543

---

When shifting from Drive into Reverse or from Reverse into Drive, a pinging type noise may be heard. This noise may also be heard when cruising and/or during acceleration or deceleration. This is not a manufacturing defect in the axle. A sealing washer (see picture below), is needed to resolve this issue (refer to Volvo TSB #77-08).

Front View - Faces Hub



Rear View - Faces Axle

